

FIGURE 1




FIGURE 2

in-line front-of-line portion 300A

V/C 302

1			plasma	W/B	plasma	
	D/A	cure		310	312	
	304	306	308	310		

in-line end-of-line portion 300B

V/C 302		V/C 302		V/C 302
mold	PMC	SBA	saw	sort
314	316	318	320	322

in-line finish portion 300C

V/C 302	V/C 302	V/C 302
mark	FVI	T/R
324	326	328





Figure 4



Flgure 5

FIGURE 6

in-line finish portion

in-line end-of-line portion

in-line front-of-line portion

300A

300B

Trash 610





FIGURE 8








FIGURE 10



ACCSSING ORBIT

7

FIGURE 12



F16 13